

BID OPENING CERTIFICATION RECO

Date of Bid Walk: 2/22/2018	Due Date: 2/29/20)18	HNS #: 18-	42		
	Address		PBE	Amount		
PUBLIC BODY ESTIMATE						
PUBLIC BODY ESTIMATE:	3529 Carlyle		#34	,114		
PUBLIC BODY ESTIMATE:		+.15	_39	1231		
PUBLIC BODY ESTIMATE:		- 15	_28	<u>, 997</u>		
PUBLIC BODY ESTIMATE:						
	BID WALK AT	TENDEES				
GHC						
GOODWILL						
JPGROUP						
BOWMAN	_			<u>.</u>		•
					\	
		2	BIDD	ERS		\supset
<u>Address:</u>	GHO	$\langle \cdot \rangle_{c}$.2.'11	TD(- /		
Addiess.		- 1		JPGROW	2 Kgon	war
13529 Carlyle	30,8	39 / 3.	7,967	33,448	2/ 31,9	<u> 2/5</u>
2.		A) V		•	1 Anha	L.
	6HC ha	10/18	uh		T BIST	3
3		c capa	<u></u>		Z DI	der
4.	6HC no			Lov	~ (~ / / / / / / / / / / / / / / / / / /	₹.
5.				do!	sacity	1
<u> </u>				CA	Thomas	TXV-
This is to cortify that hid for the	Sala Sala and Card at the second second			/W	21.	
This is to certify that bids for the Office located at 600 E. Trade Str	eet, Charlotte, NC/	icly opened an	d read aloud in	the Neighborho	od & Business S	3ervicès
	1 /					
Bids Opened By:	n full Bi	ds Recorded B	y:	7/1/11		
Witnessed By: 15/1		ate:		3/ /	18	
Note: Responsive bids are tho	se which fall within a range of 1	5% above and	15% below the	oo vhod sildug	t estimate As	a
	responsive bid is recommended				Journator 73	

Property Details

Prepared By: City of Charlotte Housing & Neighborhood Services 600 E. Trade Street Charlotte, NC 28202 (704) 336-7600

Address:	3529 Carlyle Dr (Addom) Charlotte, NC 28208			Lindsay	.r
	Chanotte, NO 20200	Owner Phone:		(704) 392-549	5
Structure Type:	Single Unit	Program(s):		- NO LEAD ome FY 2018	
Square Feet:	990		Gaigin	011101112010	
Year Built:	1955				
Property Value:	68700				
Tax Parcel:	06109505				
Census Tract:					
Property Zone:	Council District 3				
Repair Category: 00	0.0 General Requirements				
<u>Description</u>			Floor	Room	<u>Exterior</u>
Permits Required				GENERAL R	EQUIREMENT Cerior
The contractor is respor	nsible obtaining and paying for all permits	required, Said permits	shall inclu	de all items in	this scope of work.
		Bld Cost:	x	· =	500
	-	Base	_^`	Quantity	Total Cost
Dumpster				GENERAL R	EQUIREME NER erior
After procuring all required debris using dust control away daily using dump	red permits, place AS MANY roll-off dump il methods. Remove dumpster and repair a trallers.	sters as needed withou any evidence of the dur	t damagir npsters u	ng the site. Co se. Contractor	llect construction may haul debris
	E	3id Cost:	Х	=_	275
		Base	(Quantity	Total Cost
Portable Tollet				GENERAL R	EQUIREME NETS erior
Provide temporary tollet	facilities from job start until approval of pe	ermanent facilities.			
	E	Bid Cost:	Х		250
		Base		Quantity	Total Cost
					•



Repair Category: 02.0 Site Improvements				
<u>Description</u>		<u>Floor</u>	Room	<u>Exterior</u>
Exterminate Termites			GENERAL RE	EQUIREMENT Region
Exterminate for termites. Drill and patch foundation year guarantee with an optional yearly renewable v	and pavement where nece varranty for the homeowner	ssary, Exterminat	or must be licens	sed and provide a 1
,	Bid Cost:	x	==	1340
		Base	Quantity	Total Cost
Repair Category: 06.0 Roof, Chimney, Gut	ters & Downspouts			
<u>Description</u>		<u>Floor</u>	Room	<u>Exterior</u>
Tear Off & Reroof Shingles (Health Homes)			EXTERIOR	Exterior
Remove and dispose of existing roofing, inspect an 30 year architectural shingles. Include ice and wate necessary accessories. (13.3)	er shield at all roof edges, fe	elt paper, shingle o	over ridge vent, b	oots, flashing and all
en e	Bid Cost:	X	=	4,050
	ers per como de commune de que proceso seguir en communicações.	Base	Quantity	Total Cost
Repair Category: 08.0 Doors & Windows				
Description		Floor	Room	<u>Exterior</u>
Vinyl Window			EXTERIOR	Exterior
Dispose of window units and any security bars. Fle windows including half screens. Insulate rough ope Exterior trim to be wrapped in PVC coated aluminu installation is to include repairing any damaged her joists and sill. (17)	ening. Install new extension m coil as needed. Repair a	jambs, casing an Il areas disturbed	d sill as needed, by removal and i	prime and paint. nstallation. This
	Bid Cost:	Х	=	4510
	<u> </u>	Base	Quantity	Total Cost



Prehung Metal Door Entrance - KITCHEN DOOR

Remove existing door, frame and threshold. Install new Energy Star rated pre-hung exterior door. Insulate cavity. Install mortised dead bolt and lever handled door hardware keyed alike. Install wide peep sight. New casing and shoe molding will match existing. Apply primer and topcoat, this installation to include repairing any damaged header, door framing, to include wall framing, sub-floor, floor joists and sill.

	Bid Cost:	Х	=	= 600	
		Base	Quantity	Total Cost	
Repair Category: 09.0 HVAC				•	
Description		Floo	-	Exterior	
Replace Duct Work with Tape Repairs			GENERAL F	REQUIREMENERSerior	
Replace all ductwork which has been taped / repaired.					
	, Bid Cost:	х	=	1500	
		Base	Quantity	Total Cost	
Fan/Light Fixture- Energy Star Bathroom			BATHROOM	II- MASTER	
	Bld Cost:	х	=	225	
		Base	Quantity	Total Cost	
Range Hood Exterior Vented - KITCHEN					
Install an exterior ducted enameled range hood with integra cabinet with screws. Include metal vent and roof or wall ca	al controls and ligh p/damper assemb	t capable of 100 ly, using #14 cop	cfm at 70 sones. oper Romex. Ow	Attach hood to ner's choice of color.	
	Did Coots	x	=	435	
	Bid Cost	Base	Quantity	Total Cost	
Register Cover Install - Master Bath					
install/replace appropriately sized baseboard return air diffu	user with latch-con	trolled single da	mper.	, , , ,	
				65	
	Bld Cost: _	Base	Quantity	Total Cost	

G.

Repair Category: 10.0 Electrical						
<u>Description</u>			Floor	Room		<u>Exterior</u>
Smoke Detector Hard Wired				GENERA	L REG	QUIREMENER Rerior
Install in 2 bedroom and middle-rear den. Install UL approved, interconnected, celling mounted smoke battery backups in bedrooms and outside of sleeping areas.	and heat detecto	rs permane	ntly wir	ed into a red	ceptac	le boxes with
balloty backage in bear constant and the						450
	Bid Cost:	Base	x	Quantity	_=	Total Cost
		Dase		Quantity		Total Cost
Combination CO / Smoke Detector Hard Wired					L REC	QUIREMENER Serior
Install a hard wired combination carbon monoxide and smok	e detector with ba	attery back	up. (35	.09)		
	Bid Cost:		х		=	3 <i>50</i>
	D , a 000 ti	Base		Quantity		Total Cost
Hald Flating Bankara				BATHRO	OM- N	MASTER
Light Fixture Replace Replace or install a ceiling mounted 2 bulb or wall mounted 4	4 hulb strip. UL at	oproved, CF	L or LE			
Replace of Illistali a ceiling modified 2 bolb of wall medified						
	Bid Cost:		_x		-=	150
		Base		Quantity		Total Cost
GFCI Receptacle 20 AMP				BATHRO		
Install a flush mounted, ground fault circuit interrupted, duple	ex receptacle and	cover plate	. Fish v	vire and rep	air all I	tear out as needed.
	Bid Cost:		х		=	225
	ыа оози	Base		Quantity		225 Total Cost
<u>/ </u>						
Replace - Switch Plate & Switch				BATHRO	OM- N	MASTER
Install a single pole switch and cover plate.						
	Bid Cost:		Х		=	65
	•	Base		Quantity		Total Cost
GFCI Receptacle 20 AMP				KITCHE	٠. ١	•
Install a flush mounted, ground fault circuit interrupted, duple	ex receptacle and	cover plate	. Fish v			tear out as needed.
Internal and internal section is a section of the s	·	•				225
	Bid Cost: _		_x_	0	_=	
		Base		Quantity		Total Cost
Secretary and the						

1867

Ceiling Fan with Light Kit

KITCHEN

Install a 52" 3 speed flush mounted ceiling fan with a minimum two bulb UL approved, CFL or LED light fixture with shade and lamps. Include ceiling fan mounting box. (35.10)

CONTRACTOR OF	ane .
20	4
THEIR	
《明显》	*

Bid Cost: X = 300

Base Quantity Total Cost

Repair Category: 11.0 Plumbing & Fixtures

Description

Floor Room

Exterior

Water heater 40 Gallon Gas

GENERAL REQUIREMENTA ferior

Remove existing water heater and all obsolete or deteriorated flue piping and gas line and dispose of properly.

Install an insulated 40 gallon, glass lined, high recovery gas water heater with a 10 year warranty and an Energy Factor of .61 or greater.

Installation includes PRV valve and extension, drain pan with drain to the exterior, expansion tank, and new gas line and flue piping through the roof as necessary to meet the requirements of the Construction Specifications and all relevant NC Codes.



Bid Cost: X = 1200

Base Quantity Total Cost

17" Height Commode Replace

BATHROOM- MASTER

Install a 17" height, 2 piece, close coupled, white, vitreous china commode with a maximum water usage per flush of 1.6 gallons. Include plastic or pressed wood white seat, supply pipe, shut-off valve, flap valve and wax seal.



Bid Cost: X = 340

Base Quantity Total Cost



Bathtub and Shower Surround 5' Fiberglass

BATHROOM- MASTER

Install a 5', white Swan or equivalent 3 piece, fiberglass shower surround. Caulking all seams and penetrations. Include new single handled tub/ shower diverter valve and drain.



Bid Cost: X = 2170

Base Quantity Total Cost

Double Bowl Sink Complete

KITCHEN

Install a 18 gauge 33" x 22" x 9" double bowl, stainless steel, self rimming kitchen sink including a single handle metal body faucet, rated at 2.0 GPM or less, with a 15 year drip- free warranty, P-trap, supply lines, full port ball type shut-off valves & escutcheon plates on all supply & drain lines. No copper compression fittings.



Bid Cost: X = 350

Base Quantity Total Cost

Waste-Line Snake

GENERAL REQUIREMENTATION

Power snake 3 baths & kitchen drains to clear lines for fixtures to main street sewer

Bid Cost: X = 450

Base Quantity Total Cost

Repair Category: 12.0 Floor

Description

Floor Room

<u>Exterior</u>

Floor System Repair

BATHROOM- MASTER

Remove all fixtures not built in. Dispose of floor assembly. Install 2"x 10" joists hung 16" on center, 3/4" subfloor. Include replacing all deteriorated band joists and insulating floor to code.

Bid Cost: X = 690

Base Quantity Total Cost

Resilient Flooring

BATHROOM- MASTER

Install 25 year warrantied resilient floor covering per manufacturer's specifications. Include transitions and painted or stained wood quarter-round at all perimeters to complete installation.



Base Quantity

Floor System Repair

KITCHEN

Remove all fixtures not built in. Dispose of decayed floor assembly only . Install 2"x 10" joists hung 16" on center, 3/4" subfloor where required. Include replacing all deteriorated band joists and insulating kitchen floor to code.

	Bld Cost:	>	(:	= 800
	Bid 003.1	Base	Quantity	Total Cost
Resilient Flooring			KITCHEN	
Install 25 year warrantied resilient floor covering per quarter-round at all perimeters to complete installa	er manufacturer's specifica tion.	lions. Include tr	ansitions and pai	nted or stained wood
	Bid Cost:	>	(:	= 990
		Base	Quantity	Total Cost



Repair Category: 13.0 Interior Wall & Trim

Description

<u>Floor</u> Room **Exterior**

Prep & Paint Room Semi Gloss

BATHROOM- MASTER

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)

Bid Cost:		X	=	375	
	Base	Quantity		Total Cost	

Wall	Finish	Repair

KITCHEN

Repair wall finish. Patch drywall or plaster holes in wall greater than one inch. All others use an adhesive mesh and mud over the mesh with the appropriate material. Wet sand smooth. (Also 26.0 - Plaster)

	Bid Cost:	x	(=	400
		Base	Quantity	Total Cost
Prep & Paint Room Semi Gloss				DINNING ROOM
Remove or cover hardware and accessories not to be painted. fungus, dirt, and dust from surfaces. Fill holes and cracks. Prim with owner's choice of low VOC acrylic SEMI-GLOSS latex. Refurniture required shall be included. (33.27)	ne all new mate	rials and spot p	orime existing with	acrylic latex. Top coat
Tallica o Joquino a cinema a c				52
2. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Bid Cost:	X Base	Quantity	Total Cost
			•	
Wallpaper Removal -Kitchen / Dinning Room / Mast.Bath			KITCHEN	
Remove existing wallpaper to a clean wall surface ready for pri	mer and paint.	Include a thin	skim coating of ligh	tweight joint
compound sanded and smoothed if needed.				ILAN
	Bid Cost:	Х	(=	780
	_	Base	Quantity	Total Cost
Drywall Entire Room - Master Bathroom				
Remove all gypsum, paneling, lathe and plaster or miscellaned code. Glue, nail and screw new drywall. Apply tape and 3 coats paint. (Also 26.0 - Plaster)	ous wall covering of joint comp	ngs to expose fo ound to achieve	raming. Add insula e a professional fin	tion as required by ish. Wet sand ready for

Bid Cost: _

Base

Quantity

Total Cost

Repair Category: 15.0 Insulation					
Description		Floo	Room		<u>Exterior</u>
Insulate Floor R-19					AWL S EAG For
Install R-19 Kraft faced batt fiberglass insulation to floor where teeth" or mesh to hold insulation in place. (24.3)	missing. Vapor	barrier must fac	e heated spac	ce. Use si	trong wire, "tiger
	Bid Cost:	x_		= (140
		Base	Quantity		Total Cost
		12 8774 887 7 H VAT 1847 1 + 133 1 March 18	er oor ewspassassinage	a stanke zvena.	gagen een een oorde en oorde oorde onde to
Repair Category: 16.0 Cabinets, Accessories & Appl		•			
Description		Floo	Room		<u>Exterior</u>
Vanity/ Counter Top/ Sink/ Mirror Replace Complete			BATHRO	OM- MAS	STER
Install new vanity cabinet complete with counter top of laminate single handled metal faucet with drain and pop-up , P- trap, sup	with vitreous c oply lines, full po	hina sink or mar ort ball type shut	ble-lite top wi -off valves & o	th preform escutched	ed sink. Include in plates.
	Bid Cost:	х		= '	550
		Base	Quantity		Total Cost
Grab Bars			BATHRO	OM- MAS	STER
Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 36 Owners choice of locations. (38.1)	" (include wood	blocking in wall	. Each bar mu	ıst hold 30	00 pounds).
	Bid Cost:	x		= 3	375
		Base	Quantity		Total Cost
Accessory Set - 3 Piece Chrome			BATHRO	OM- MAS	STER
Install a chrome plated steel bathroom accessory set consisting	g of a 24" towel	bar, hand towel			
	Bid Cost:	.,		=	125
	Più 0091'	Base	Quantity		Total Cost
		•			



Cal	hina	ite I	Mall

KITCHEN

Replace wall cablnets. Cabinets are to be constructed of solid maple and plywood. No particle board allowed. See contractor's manual guidelines & specifications for full requirements.

- 278777474
一种,这个人,
建 . 作为。在
\$ 100 miles
A 3
1954
Was a facility of the
AND REAL PROPERTY OF THE PROPE

Bid Cost: X = 1450

Base Quantity Total Cost

Cabinets Base

KITCHEN

Replace base cabinets. Cabinets to be constructed of solid maple and plywood. No particle board allowed. See contractor's manual guidelines & specifications for full requirements.



Bid Cost: X = 100

Base Quantity Total Cost

Counter Tops Replace

KITCHEN

Screw to base cabinet a square edged plastic laminate counter top. Provide end-caps and cutout for sink. Caulk counter top to adjoining walls with low VOC caulking to match wall color. Owner's choice of in-stock color and texture. (32.10)



Bid Cost: X = 775

Base Quantity Total Cost

Repair Category: 17.0 Stairs & Steps

Description

Floor Room

Exterior

Exterior Handrails (Decayed Wood)

STAIRS & STEPS

Remove any decayed wood, replace, paint two coats matching low VOC paint.



Bid Cost: X = 734

Base Quantity Total Cost

2/22/2018

Certification

Signature: Jaluary Johns

2/22/2018